

## MARYLAND DEPARTMENT OF THE ENVIRONMENT



1800 Washington Boulevard ● Baltimore MD 21230 410-537-3000 ● 1-800-633-6101

Martin O'Malley Governor Robert M. Summers, Ph.D. Secretary

Anthony G. Brown Lieutenant Governor

October 3, 2012

Lorie Baker Site Assessment and Non-NPL Federal Facilities Branch (3HS12) US EPA Region III 1650 Arch Street Philadelphia, PA 19103-2029

RE: Pre-CERCLIS Screening Report for the Brusowankin & Sons Dry-Cleaners Site

Dear Ms. Baker:

Enclosed are the Pre-CERCLIS screening report and Site Discovery forms for the Brusowankin & Sons Dry-Cleaner site drafted by the Maryland Department of the Environment, Federal Assessment and Remediation Division (MDE). The report addresses a site identified in the *Maryland Dry-Cleaner Initiative* report.

The objectives of the Pre-CERCLIS screenings are to categorize those sites identified in recent site initiatives which, (1) may need further investigation, and (2) need no further investigation. MDE performed screenings for the site and determined that there is sufficient cause to proceed with further investigation.

The enclosed Pre-CERCLIS Screening Report is submitted in accordance with the current cooperative agreement. If you have additional questions concerning this matter, please contact me at (410) 537-3449.

Sincerely,

Alex M. Cox, Project Manager

Federal Assessment and Remediation Division

## Enclosure

cc:

Mr. Horacio Tablada

Mr. James Carroll

Ms. Peggy Smith

PRE-CERCLIS SCREENING ASSESSMENT CHECKLIST/DECISION FORM
This checklist can assist the site investigator during the Pre-CERCLIS screening. It will be a second to the site investigator during the Pre-CERCLIS screening. This checklist can assist the site investigator during the Pre-CERCLIS screening. It will be used to determine whether further steps in the site investigation process are required under CERCLA. Use additional sheets, if necessary.

Ch	ecklist Preparer:							
	•	(Name/Title)	(Date)					
		1800 Washington Blvd. Baltimore, MD 21230						
		(Address)	(Phone)					
		Acox@mde.state.md.us						
		(E-Mail Address)						
Sit	e Name:	Brusowankin & Sons						
	Diasonatini & Soiis							
n	Pravious Names (if any).							
Pre	Previous Names (if any):							
Site Location:		925 E. Baltimore Street						
		(Street)						
		Dahiman	MD					
		Baltimore (City)	, <u>MD</u> - (ST) (Zip)					
			, , , , ,					
I.aí	itude: 39.290425°	Langit	ude: -76.603444°					
1144		Dongit	70.003 111					
Co	mplete the following c	hecklist. If "yes" is marked, please exp	lain below.	YES	NO			
1.	Does the site already app	pear in CERCLIS?			X			
2.		ucts that are part of the structure of, and result	in evacure within residential buildings or					
۷.	-	•	in exposure within, residential buildings of		x			
	businesses or community							
3.		a release of a naturally occurring substance in			x			
	naturally occurring processes or phenomena, from a location where it is naturally found?							
4.	Is the release into a public or private drinking water supply due to deterioration of the system through ordinary use?				X			
5.	Is some other program actively involved with the site (i.e., another Federal, State, or Tribal program)?							
6.	Are the hazardous substa	ances potentially released at the site regulated	under a statutory exclusion (i.e., petroleum, natural					
	gas, natural gas liquids,	synthetic gas usable for fuel, normal applicati	on of fertilizer, release located in a workplace,		x			
	naturally occurring, or re	egulated by the NRC, UMTRCA, or OSHA)?						
7.			by policy considerations (e.g., deferral to RCRA					
••	Corrective Action)?		(		X			
8.	•	pentation that clearly demonstrates that there is	s no potential for a release that could cause adverse					
0.		-						
			l investigation equivalent data showing no release		x			
	•	•	at no hazardous substance releases have occurred					
	EPA approved risk asses	ssment completed) ?						
Ple	ase explain all "yes" a	nswer(s), attach additional sheets if ne	cessary:					

<b>United States</b>
Environmental
Protection Agency

## POTENTIAL HAZARDOUS WASTE SITE

I. IDENTIFICATION							
01 ST	02 SITE NUMBER						
MD							

Environmental Protection Agency	rotection Agency SITE IDENTIFICATION ("DISCOVERY")  O1 ST O2 SITE NUMBER  MD					ER		
II. SITE NAME A	ND LOCATION	÷				ð Mil		
01 SITE NAME (Legal, common		02 STREET, ROUTE NUMBER, OR SPECIFIC LOCATION IDENTIFIER						
Brusowankin & Sons				E. Baltimo	re Street			
03 CITY			04 ST	05 ZIP CODE	06 COUNTY		07 CO CODE	08 CONG DIST
Baltimore			MD		Baltimore City			03
09 DIRECTIONS TO SITE (Sta	ting from nearest public road; enter up	to 4 lines of text)						
	Saltimore, Corner of Cha at 925 E. Baltimore Stro		nore S	treets. Pro	oceed east on Balt	imore	Street for	) blocks.
III. RESPONSIBL	E PARTIES				7		12.30 (2) (2) (2) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4	
01 OWNER (If known)			02 STRE	ET (Business, re	esidential, mailing)			
03 CITY			04 ST	05 ZIP CODE	06 TELEPHONE NUMBER	1		
07 OPERATOR (If known and o	lifferent from owner)		08 STRE	ET (Business, re	esidential, mailing)	-		
***************************************				<del></del>	<del></del>			
09 CITY			10 ST	11 ZIP CODE	12 TELEPHONE NUMBER	l		
				<u> </u>				<del></del>
13 TYPE OF OWNERSHIP (Ma					0.07475		D 001111	
_X_ A. PRIVATE _ E. MUNICIPAL	B. FEDERAL (Agency F. OTHER (Specify): _	лате):			_ C. STATE _ G. UNKNOWN		_ D. COUNT	Y
IV. HOW IDENTIFI	ED The state of th		3.14.			iv		÷:
01 DATE IDENTIFIED	02 IDENTIFIED BY (Mark all that app	ly; use "insert" mode)						
August 22, 2012  - A. CITIZEN COMPLAINT - D. AERIAL RECONNAISSANCE - G. OTHER EPA IDENTIFICATION - H. OTHER (Specify):  - A. CITIZEN COMPLAINT - E. RCRA INSPECTION - F. SURFACE IMPOUNDMENT ASSESSMENT - F. SURFACE IMPOUNDMENT ASSESSMENT								
V. SITE CHARACT							4	
01 TYPE OF SITE (Mark all that								
A. STORAGE!	B. TREATMENT C. DISF	POSAL D. U	NAUTH	ORIZED DU	MPING X E. OTHE	ER (Specil	y): Vapor Int	rusion
	OBLEMS (Provide narrative description		xt)					
Dry cleaner operate	ed on site for >50 years.							
03 SUMMARY OF ALLEGED	OR POTENTIAL PROBLEMS (Provide	le narrative description; e	enter up to	5 lines of text)				
Vapor intrusion iss	ues relative to a historic	dry cleaning o	peration	on.				
VI. INFORMATIO	N AVAILABLE FROM	M.			5			à 1
01 CONTACT 02 OF (Agency/Orga			unization)				03 TELEPHONE NUMBER	
Alex Cox		MDE					410-537-	3449
04 PREPARED BY		05 AGENCY	06 ORGA	ANIZATION	07 TELEPHONE	NUMBR	08 DATE (Mon	
Alex M. Cox					410-537-34	149	08/22/12	

ORIGINAL
----------

☐ The site is not recommended for placement into CERCLIS.

☐ More Information Needed.

DECISION/DISCUSSION/RATIONALE: (LEVEL 2 site: Operation >50 Years, Dry Cleaning Equipment and Suppliers) The site of Brusowankin & Sons is a three story block and brick structure in a residential commercial area just east of downtown Baltimore City. The building is currently vacant and boarded up pending the urban renewal taking place in the block. The buildings east of the site have recently been rehabilitated and several other structures are in the process of rehabilitation. A new grass lot separates the 925 structure from the adjacent structure to the east. The area is in the process of gentrification; old buildings are being rehabilitated and turned into new apartments and townhomes. Drinking water in the area is supplied by the City of Baltimore. The new residential housing has a potential for vapor intrusion issues.



